

Infrared photos from water infiltration of Coffey Hall – August 23, 2006 - Room 90C



Room 90C Northwest corner – Area of water damage. The dark area on the IR photo has elevated moisture levels.



This is an area of fungal growth on the south wall of room 90 C. The Dark IR image on the left indicates an area of elevated moisture.



This is a photo of the west wall of room 90C showing an area of fungal growth. The Dark IR image on the left indicates an area of elevated moisture.

Coffey Hall August 23, 2004



Room 90D Coffey hall northwest corner of room – infrared camera shot of location under cabinet. The wet carpet under the cabinet shows up as a dark image.



Base board West wall in 90 D – dark area IR photo has elevated moisture levels.