

Below grade mechanical spaces are prone to problems with water infiltration



Williamson Hall flooded floor of mechanical space - April, 2006



Standing water inside air handling unit – April, 2006



Slime on floor adjacent to ineffective perimeter drain system – April, 2006