

HVAC ventilation ducts within soil



Sand and debris in childcare center below ground ductwork prior to flood in August 2006



Debris on top edge of duct after filling with water – August 2006



Sub slab ventilation ducts with standing water University Childcare center August, 2006



Mud and water discharged from below grade duct at University Childcare center August, 2006.