

Walter Library flooding of raised floor



Area of flooding – December 2005



Rusting floor supports and mold growth below raised floor on sheetrock



Closeup of fungal growth.



Standing water beneath floor